

Work Order ID 73200

Friday, August 26, 2011 7:07:57 AM



Page 1

Item ID: D2235-1

Accept



Setup Start



Revision ID:

Stop



Item Name: Basket Rib

Start Date: 8/26/2011 Start Qty: 10.00



Cust Item ID:

Required Date: 8/31/2011 Req'd Qty: 10.00



Customer:

Reference:

Approvals:

Process Plan: CL

Date: 11/08/26

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D2235

Rev B1

100

0.00



Large Fab

Large Fab

Memo

0.00

Large Fab

1- Pick D3166-1 and cut as per dwg D2235 using DT8302 □2- remove identification markings on tube □3- deburr

11/11/29 (10x)

110

0.00



QC6- Inspect dimensions to drawing

QC

Memo

0.00

Quality Control

11/11/29 (10x)

120

0.00



Identify as per dwg & Stock Location:

Packaging

Basket cell
Memo

0.00

Packaging

11/11/29 (10x)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 73200

Friday, August 26, 2011 7:07:57 AM



Page 2

Item ID: D2235-1

Accept



Setup Start



Revision ID:

Stop



Item Name: Basket Rib

Start Date: 8/26/2011 Start Qty: 10.00



Cust Item ID:

Required Date: 8/31/2011 Req'd Qty: 10.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130

QC21 - Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

11/11/30

MF
11-11-30

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Friday, August 26, 2011 7:07:55 AM

Page 1

Work Order ID: 73200



Parent Item: D2235-1



Parent Item Name: Basket Rib

Start Date: 8/26/2011

Required Date: 8/31/2011

Start Qty: 10.00

Required Qty: 10.00

Comments: IPP Rev:A New Issue 08-12-01 DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D3166-1		Manufactured	No			100	Each	15.0000	1	10			
---------	--	--------------	----	--	--	-----	------	---------	---	----	--	--	--



Basket Hoop



373608 → 10x

Location

Loc Qty

Loc Code

WA

15

70924

4

72589

11

11/11/29

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries




DESIGN B WILLIAMS	DRAWN BY B WILLIAMS	DART AEROSPACE LTD VICTORIA INTERNATIONAL AIRPORT, CANADA	
CHECKED <i>BW</i>	APPROVED <i>BW</i>	DRAWING NO. D2235	REV. B SHEET 1 OF 1
DATE 94:12:16		TITLE BASKET RIBS	SCALE
BI 02.08.06 <i>U-1</i>		CAN BE MADE FROM D3166-1	


RELEASED
R 960507

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 13200

CL 11/08/26



D2235-1



D2235-3

CAN BE MADE FROM D3166-1 *BI*
MATERIAL: 304/316 SS, 3/4 X 3/4 X 0.063 WALL SQR.